

IE-352

Section 1, CRN: 13536

Section 2, CRN: 30521

First Semester 1432-33 H (Fall-2011) – 4(4,1,1)

MANUFACTURING PROCESSES - 2

Sunday, Dec 18, 2011 (23/01/1433H)

MIDTERM 2 [10 POINTS]

Name:	Student Number: 4	Section: 8:00 / 10:00
-------	----------------------	--------------------------

Place the correct letter in the box at the right of each question [$\frac{1}{2}$ Point Each]

Questions 1-4. In an orthogonal cutting operation, a cast-cobalt alloy tool (where $V_{T=1 \text{ min}} = 220 \frac{m}{min}$) was first used in machining a workpiece using the following parameters: $V = 150 \frac{m}{min}$, $t_o = 0.15 \text{ mm}$, $\alpha = 12^\circ$ and the width of cut = 5 mm. This resulted in a tool life of 40 min, $t_c = 0.20 \text{ mm}$, $F_c = 600 \text{ N}$ and $F_t = 350 \text{ N}$. The process was then repeated under similar conditions at half the cutting speed.

1. What is the percent change in *tool life* between the two operations?

- a. a 793-fold increase (i.e. 79,300 %)
- b. a 792-fold increase (i.e. 79,200 %)
- c. a 6.9-fold increase (i.e. 690 %)
- d. a 397-fold increase (i.e. 39,700 %)
- e. a 396-fold increase (i.e. 39,600 %)

2. What is the percent change in *material cut* between the two operations?

- a. a 793-fold increase (i.e. 79,300 %)
- b. a 792-fold increase (i.e. 79,200 %)
- c. a 6.9-fold increase (i.e. 690 %)
- d. a 397-fold increase (i.e. 39,700 %)
- e. a 396-fold increase (i.e. 39,600 %)

3. What is the value of the *friction angle* for the first process? ☐
- a. 12.0°
 - b. 30.3°
 - c. 42.3°
 - d. 18.3°
 - e. 47.7°
4. What is the percentage of the total energy that goes into overcoming *friction* at the tool–chip interface in the first process? ☐
- a. 22.1 %
 - b. 77.9 %
 - c. 45.4 %
 - d. 58.4 %
 - e. 54.6 %
5. The process involving a rotating cutter that produces a cavity is called ... ☐
- a. end milling
 - b. slab milling
 - c. cutting off
 - d. straight turning
 - e. skiving
6. The process involving a cutting tool that moves radially inward is called... ☐
- a. end milling
 - b. slab milling
 - c. cutting off
 - d. straight turning
 - e. skiving
7. The angle formed between the flank face and the workpiece is called the... ☐
- a. inclination angle
 - b. friction angle
 - c. shear angle
 - d. rake angle
 - e. relief angle

8. Which of the following is a *dependent* variable in the cutting process?

☐

- a. cutting speed
- b. tool material
- c. tool surface finish
- d. energy dissipated during cutting
- e. cutting fluids

9. What type of chips can develop a *secondary* shear zone?

☐

- a. built-up edge chips
- b. continuous chips
- c. serrated chips
- d. discontinuous chips
- e. chip curls

10. The *thrust* force experienced in cutting...

☐

- a. may push the tool away from the workpiece if too high
- b. acts at the shear zone to remove layers of material from the workpiece
- c. is also known as the specific cutting force
- d. supplies the energy required for cutting
- e. acts along the tool-chip interface

11. Removing a large amount of material at high speeds is termed...


☐

- a. shaving
- b. skiving
- c. finish machining
- d. rough machining
- e. end milling

12. Label the diagram shown on the right.

☐

- a. P: rake face; Q: flank face; Y: shear zone; Z: workpiece
- b. P: flank face; Q: rake face; Y: shear plane; Z: chip
- c. P: rake face; Q: flank face; Y: shear zone; Z: chip
- d. P: flank face; Q: rake face; Y: shear zone; Z: chip
- e. P: rake face; Q: flank face; Y: shear plane; Z: chip



13. Which of the following scenarios usually involves *more* power consumption? ☐

- a. using a negative rake angle as opposed to a positive rake angle
- b. low friction at the tool-chip interface friction as opposed to high friction
- c. using sharp tools as opposed to dull tools
- d. machining magnesium alloys as opposed to stainless steels
- e. machining aluminum alloys as opposed to titanium alloys

14. Where does the maximum *increase* in temperature occur during cutting? ☐

- a. about half-way up the tool-chip interface
- b. at the tool-tip
- c. at the middle of the shear zone
- d. about half-way up the flank face
- e. at the location where the chip leaves the rake face

15. Which of the following can measure temperature generated in the cutting zone? ☐


- a. dynamometer
- b. calculating specific energies for shear and friction
- c. load cell
- d. radiation pyrometer
- e. transducers that measure acoustic emissions

16. Which of the following can be used to monitor cutting tool condition? ☐

- a. dynamometer
- b. calculating specific energies for shear and friction
- c. load cell
- d. radiation pyrometer
- e. transducers that measure acoustic emissions

17. Label the diagram shown on the right. ☐

- a. P: flank face; Q: rake face; Y: chip; Z: flank wear
- b. P: rake face; Q: flank face; Y: chip; Z: nose wear
- c. P: rake face; Q: flank face; Y: chip; Z: crater wear
- d. P: flank face; Q: rake face; Y: chip; Z: crater wear
- e. P: rake face; Q: flank face; Y: chip; Z: flank wear



18. Which of the following has the greatest effect on surface *finish*?

☐

- a. feed marks
- b. high temperatures generated during cutting
- c. tool vibration and chatter
- d. the built-up edge
- e. dull tools

19. Which of the following has the largest effect on surface *integrity*?

☐

- a. feed marks
- b. high temperatures generated during cutting
- c. tool vibration and chatter
- d. the built-up edge
- e. dull tools

20. Which of the following is a safe, non-ferrous metal, with high machinability?

☐

- a. Tungsten
- b. Cold-worked carbon steel
- c. Aluminum
- d. Leaded steels
- e. Magnesium

Equations, Diagrams You May Find Useful

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha} \Rightarrow r = \frac{t_0}{t_c} = \frac{\sin \phi}{\cos(\phi - \alpha)}$$

$$\alpha_e = \sin^{-1}(\sin^2 i + \cos^2 i \sin \alpha_n)$$

$$T = \frac{0.000665 Y_f}{\rho c} \sqrt[3]{\frac{V t_0}{K}}$$

$$r = \frac{t_0}{t_c} = \frac{V_c}{V}$$

$$T_{mean} \propto V^a f^b$$

$$\gamma = \frac{AB}{OC} = \frac{AO}{OC} + \frac{OB}{OC} \Rightarrow \gamma = \cot \phi + \tan(\phi - \alpha)$$

$$VT^n = C$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$

$$VT^n d^x f^y = C$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2}$$

$$T = C^{1/n} V^{-1/n} d^{-x/n} f^{-y/n}$$

$$\Rightarrow \phi = 45^\circ + \alpha - \beta \text{ (when } \mu = 0.5 \sim 2)$$

$$T \approx C^7 V^{-7} d^{-1} f^{-4}$$

$$\text{Power} = F_c V$$

$$\text{Power for friction} = F V_c$$

$$\text{Power for shearing} = F_s V_s$$

$$R_t = \frac{f^2}{8R}$$

$$r = \frac{t_0}{t_c} = \frac{V_c}{V}$$

$$u_t = u_s + u_f \quad u_s = \frac{F_s V_s}{w t_0 V}$$

$$u_f = \frac{F V_c}{w t_0 V} = \frac{F r}{w t_0}$$

$$\mu = \frac{F}{N} = \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_n = F_c \sin \phi + F_t \cos \phi$$

$$F_t = R \sin(\beta - \alpha) \text{ or } F_t = F_c \tan(\beta - \alpha)$$

